

WAX CARE

Hydrorepellent dispersion of waxes



Description

WAX CARE is a hydrorepellent dispersion of waxes for the intensive maintenance of lacquered (solvent, water) oiled and/or waxed wooden floor and also for internal cotto tiles, stones, etc. WAX CARE gives to the surface a pleasant natural and hydrorepellent effect. Its special formulation renews, protects and restores dull, scratched or ruined wooden floors.

Characteristics

Appearance	liquid
Application temperature	+10°C ÷ +25°C
Application	spray, cloth, wax applicator, buffing machine
Thinning (if necessary)	LIOS SOLV / DILUENTE DRV1
Fingerprint dry	30' ⁽¹⁾
Complete hardening	12-24 h ⁽¹⁾
Coverage	70-90 m ² /L
Storage stability	1 year ⁽²⁾
Packaging	0,5L - 1L - 5L
Tool cleaning	DILUENTE DNE

1 at 20°C and 65% R.H.

2 in original sealed containers at temperatures between +10°C and +25°C

Available Versions

WAX CARE: transparent for intensive maintenance.

WAX CARE COLORATO: colored for the restoring of faded and tinted wooden floors.

How to use

Shake well before use.

Apply WAX CARE by spraying on the part of the floor to be treated, use a cloth to spread the product uniformly to avoid accumulation of product. Be carefull, do not leave any excess of the product on the surface.

After 30 minutes and complete dryness, polish the surface by cloth or disc buffing machine.

Regular maintenance has to be done with WAX CARE, applying another coat of the product.

Cleaning has to be done using the suitable cleaner: VELUREX Cleaner Star, LIOS Kronos o LIOS Soft Balm (see technical data sheets). It is not recommended to use aggressive or abrasive cloths.

Note: the application of the WAX CARE onto poorly absorbent surfaces can increase slipperiness, especially in presence of water or high humidity levels. It is suggested to make some preliminary test.

Prolonged exposures at temperatures below +10°C cause products thickening. Set the product at temperatures above +15°C before the use.

Warnings

Keep away from frost during transit and storage. Avoid prolonged exposure to temperatures below +10°C.

Label elements

· Repeated exposure may cause skin dryness or cracking.

· Do not breathe dust / fume / gas / mist / vapours / spray. · Use only outdoors or in a well-ventilated area.

Web link

Be sure to have the latest version of this technical data sheet downloadable also from the following link:



http://www.chimiver.com/tds/EN_WAX_CARE.pdf